

**SO # 111062**

**SERVICE ORDER**



Printed 01/17/2023 12:56:35 PM

**INTERNAL COPY - \*\* IN PROGRESS \*\*** User

118

Page 1

<b>Customer No</b> 1		<b>Advisor</b> Ryan Uliski	<b>Promised</b> 01/03/2023 7:11 PM	<b>Tag</b>
PINERIDGE FORD SALES		<b>Shop</b> S1	<b>Opened</b> 01/03/2023 9:27 AM	<b>Location</b>
MEADOW LAKE, SK S9X 1Z5		<b>Priority</b>	<b>Cashiered</b>	<b>PO #</b>
<b>Home</b>	<b>Bus</b> (306) 236-1810	<b>License No</b>	<b>Odometer In</b>	<b>Odometer Out</b>
<b>Cell</b>	<b>Today</b>	2018 FORD	81885	81885
<b>Email</b> kevin@pineridgeford.com		<b>Year</b>	<b>Make</b>	<b>Model</b>
		2018	FORD	ECOSPORT
		<b>Vehicle ID No</b>	<b>Selling Dealer</b>	<b>Extended Warranty</b>
		MAJ3P1TE2JC166791	01	FORD
		<b>Engine Size</b> 1.0L ECOBOOST		<b>Fleet #</b>
	<b>Term</b> CASH			<b>Stock No</b> N7089A
				<b>Colour</b> CANYON
				<b>Delivery Date</b>

Request	Description	Job	CSR	Status
015-ESP99P	USED INSPECTION Includes: Safety Inspection, Mechanical Inspection, Body and Trim Inspection, and Engine Oil and Filter (PARTS EXTRA)	1	213	Original
Labour	Description	Type	Tech	Amount
L-ESP99P	LABOUR - ESP USED VEHICLE INSPECTION	I	94	193.20
Technician	94 -			
				Parts Total 0.00
				Labour Total 193.20
				<b>Request Total 193.20</b>

Request	Description	Job	CSR	Status
008-DIAG	DIAGNOSE oil leak	2	213	Approved
Labour	Description	Type	Tech	Amount
008-DIAG	DIAGNOSE oil leak	I	94	0.00
Technician	94 -			
				Parts Total 0.00
Cause	verified oil leak cleaned oil off valve cover and road tested seem like the oil is seeping though the valve cover at join section in the vavle cover recommend replacing valve cover and seals			Labour Total 0.00
				<b>Request Total 0.00</b>
Correction	repaired on RO 111063			

Request	Description	Job	CSR	Status
000-NOISE	DIAGNOSE park aid	3	213	Approved
Labour	Description	Type	Tech	Amount
000-NOISE	DIAGNOSE park aid	I	94	0.00
Technician	94 -			
				Parts Total 0.00
Cause	verified park aid not wokring scanned for DTC got B1B44,B1B46, B1B48, B1B50 in PAM inspected wires found wires broken at a previous repair close to conector C 410 will need pigtail to repair as the wires are too short			Labour Total 0.00
				<b>Request Total 0.00</b>
	need pig tail for C410 male side			
Correction	repaired on RO 111063			

Request	Description	Job	CSR	Status
006-DIAG	DIAGNOSe reverse light	4	213	Approved
Labour	Description	Type	Tech	Amount
006-DIAG	DIAGNOSe reverse light	I	94	0.00
Technician	94 -			
				Parts Total 0.00
Cause	verified RR reverse lamp is not working inspeded bulb asseby found wires going to the reverse light conecotor is damaged and need to be replaced need pigtail for connector C 461			Labour Total 0.00
				<b>Request Total 0.00</b>
Correction	repaired on RO 111063			

Request	Description	Job	CSR	Status
016-BRONZE	BRONZE CLEAN - MID TO HEAVY CLEAN (With Light Steam) Includes: Exterior Wash/Shammy Windows Inside/Outside Vacuum Seats/Floors Wipe Down Interior Spray Vinyl Mats Wipe Down Engine Compartment Chrome Shine	5	213	Approved
Labour	Description	Type	Tech	Amount
016-BRONZE	BRONZE CLEAN - MID TO HEAVY CLEAN (With Light Steam) Includes: Exterior Wash/Shammy Windows Inside/Outside Vacuum Seats/Floors Wipe Down Interior Spray Vinyl Mats	IDET	217	319.00

SO # 111062

SERVICE ORDER



Printed 01/17/2023 12:56:35 PM

INTERNAL COPY - \*\* IN PROGRESS \*\*

User

118

Page 2

**Customer No** 1  
 PINERIDGE FORD SALES  
 MEADOW LAKE, SK S9X 1Z5  
**Home** **Bus** (306) 236-1810  
**Cell** **Today**  
**Email** kevin@pineridgeford.com  
**Term** CASH

**Advisor** Ryan Uliski **Promised** 01/03/2023 7:11 PM **Tag**  
**Shop** S1 **Opened** 01/03/2023 9:27 AM **Location**  
**Priority** **Cashiered** **PO #**

**License No** **Odometer In** **Odometer Out** **InServ Date** **Stock No**  
 81885 81885 06/07/2019 N7089A  
**Year** **Make** **Model** **Model No** **Colour**  
 2018 FORD ECOSPORT P1T CANYON  
**Vehicle ID No** **Selling Dealer** **Extended Warranty** **Delivery Date**  
 MAJ3P1TE2JC166791 01 FORD  
**Engine Size** 1.0L ECOBOOST **Fleet #**

Wipe Down Engine Compartment  
 Chrome Shine

Technician 217 -  
 Cause clean is done  
 Correction wiped inside  
 vacuumed floor and seats  
 steam cleaned floor  
 washed outside  
 wiped windows inside and out

Parts Total 0.00  
 Labour Total 319.00  
**Request Total 319.00**

Request	Description	Job	CSR	Status		
S-SUBLET	SUBLET glass	6	213	Approved		
Labour	Description	Type	Tech	Amount		
S-SUBLET	SUBLET glass	I	999	150.00		
Part	Description	Shp	Bin	Type	Price	Amount
GN1Z 5803100 AK	GLASS - WINDSCREEN	1	SPORD	I	495.99	495.99
Technician	999 -	Parts Total				495.99
Cause	install windshield	Labour Total				150.00
Correction	install windshield	<b>Request Total</b>				<b>645.99</b>

Request	Description	Job	CSR	Status		
FLOOR	install floor linears	7	213	Approved		
Labour	Description	Type	Tech	Amount		
FLOOR	install floor linears	I-ACC	94	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
GN1Z 6113300 FA	KIT - FLOOR CONTOUR	1	SPORD	IACC	241.50	241.50
Technician	94 -	Parts Total				241.50
Cause	customer requested	Labour Total				0.00
Correction	installed floor liners	<b>Request Total</b>				<b>241.50</b>

Request	Description	Job	CSR	Status		
000-INFO	grab handle	8	213	Approved		
Labour	Description	Type	Tech	Amount		
000-INFO	grab handle	I	999	0.00		
000-INFO	grab handle	I	94	107.40		
Part	Description	Shp	Bin	Type	Price	Amount
DS7Z 4273 AF	CAP - SCREW	2	SPORD	I	9.99	19.98
W502665 S437	SCREW	4	SPORD	I	8.99	35.96
G1EZ 5831406 AA	HANDLE - ASSIST	1	SPORD	I	37.99	37.99
Technician	94 -	Parts Total				93.93
Cause	found on inspection	Labour Total				107.40
Correction	installed new door handle	<b>Request Total</b>				<b>201.33</b>

Request	Description	Job	CSR	Status		
000-INFO	tow hook cover	9	213	Approved		
Labour	Description	Type	Tech	Amount		
000-INFO	tow hook cover	I	999	0.00		
000-INFO	tow hook cover	I	94	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
GN1Z 17K922 A	COVER	1	SPORD	I	10.01	10.01
Technician	94 -	Parts Total				10.01

SO # 111062

SERVICE ORDER



Printed 01/17/2023 12:56:35 PM

INTERNAL COPY - \*\* IN PROGRESS \*\* User

118

Page 3

**Customer No** 1  
 PINERIDGE FORD SALES  
 MEADOW LAKE, SK S9X 1Z5  
**Home** **Bus** (306) 236-1810  
**Cell** **Today**  
**Email** kevin@pineridgeford.com  
**Term** CASH

**Advisor** Ryan Uliski **Promised** 01/03/2023 7:11 PM **Tag**  
**Shop** S1 **Opened** 01/03/2023 9:27 AM **Location**  
**Priority** **Cashiered** **PO #**

**License No** **Odometer In** **Odometer Out** **InServ Date** **Stock No**  
 81885 81885 06/07/2019 N7089A  
**Year** **Make** **Model** **Model No** **Colour**  
 2018 FORD ECOSPORT P1T CANYON  
**Vehicle ID No** **Selling Dealer** **Extended Warranty** **Delivery Date**  
 MAJ3P1TE2JC166791 01 FORD  
**Engine Size** 1.0L ECOBOOST **Fleet #**

Cause found missing on inspection Labour Total 0.00  
 Correction installed new cover Request Total 10.01

Summary

Pay Type	Labour	Parts	Fees	Misc	Supplies	Sublet	Env	Ded	GST	PST	Total
C	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
W	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
I	769.60	841.43	0.00	0.00	69.17	0.00	0.00	0.00	0.00	0.00	1,680.20
Total	769.60	841.43	0.00	0.00	69.17	0.00	0.00	0.00	0.00	0.00	1,680.20

INTERNAL

ACCOUNT	DESCRIPTION	TYPE	CONTROL #	AMOUNT	COMMENTS
P136000	INV-USED TRUCKS		N7089A	1680.20	166791 - 2018 FORD ECOSPORT SE FWD