

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Customer

Name PINERIDGE FORD SALES
Address BOX 2380
City MEADOW LAKE, SK
Postal Code S9X 1Z5
PhoneNumber (306) 236-1810(w)
Email kevin@pineridgeford.com

Inspection

Service Order 111062
Advisor Ryan Uliski
Tech Bobby Johnston

Exterior of the vehicle

vehicle modifications Pass
Comments:
exterior lights operational Fail
Comments: right rear reverse lamp out
exterior damage Fail
Comments: rear swing gate dent, left rear quarter panel has dent
windshield: cracked, chipped or sandblasted Fail
Comments: cracked
windshield, driver and passenger front windows aftermarket tint Not Applicable
Comments:

Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More
Caution: 4/32" - 5/32"
Fail: 3/32" or less
Left front tire tread depth Pass
Right front tire tread depth Pass
Left rear tire tread depth Pass
Right rear tire tread depth Pass
Inspect overall tire wear and condition
Comments: RF 7/32 LF 7/32 RR 7/32 LR 6/32
Wheel Retorque
Wheel Torque Spec FT/LBS: 100

Vehicle

VIN MAJ3P1TE2JC166791
Year 2018
Make FORD
Model ECOSPORT
Engine 1.0L ECOBOOST
Fuel Gasoline
Stock Number N7089A
License/Stock
Date In 01/03/2023 9:27:50 AM
Completed Date 01/03/2023
Odom 81885

Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Fail
Comments: oil is leaking some where on the vavle cover
Air Inlet system: air filter, filter box and inlet tube are clean Pass
Comments:
Emission System: visually inspect to ensure all components are intact with no modifications Pass
Comments:
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass
Comments:
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass
Comments:
Power Steering: pump, gear, and hoses have no leaks or damage Not Applicable
Comments:
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass
Comments:
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass
Comments:
Brake System: no leaks or damage. Fluid is at proper level and clean Pass
Comments:
Inspect cabin air filter and report findings Fail
Comments: Dirty

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering System and Linkage: no leaks damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension System: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Axles: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Exhaust System: no leaks, damage. All components in place including convertors	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Frame/Undercarriage: examine for damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Trailer Plug: harness intact, plug tested with trailer DR.	Not Applicable	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments: : No				
Spare Tire, jack, and tools	Caution	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments: not stored in ther location				

Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)				
Caution: 4mm-5mm (disc), 2mm (drum)				
Fail: 3mm or less (disc), 1mm (drum)				
Measure front brake lining thickness	Yellow	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Thickness: 4				
Measure rear brake lining thickness	Fail	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Thickness: 3				
Inspect brake system components	Yellow	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake Rotor Thickness MM				
Left Rear: 1136				
Right Rear: 1038				
Left Front: 2450				
Right Front: 2435				

Additional Recommendations

Additional Recommendations
Comments: grab hand;e o right front missing cover for tow hook missing on rear bumper

Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Transmission Performance: shifts smoothly with no unusable noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering: steering is tight and responsive with no unusual characteristics or noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension: vehicle exhibits no sign of harshness or loose suspension	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
A/C and Heater: operating properly with no unusual noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Cruise Control: operating properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Vibration/Noise: no unusual vibration or noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Warning Lights - No warning lights illuminated while operating the vehicle	Fail	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments: parrk aid fault				
Wipers/Washer: no streaks or inconsistent spray	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Guages: working correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power Seats: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Lights: functioning correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Horn: operates correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Windows/Locks: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Mirrors- Operate correctly (power and manual)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Moonroof	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Clock/Audio System	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Other Switches/Controls	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Heated Backglass	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power outlets work	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				