

# PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH  
MEADOW LAKE, SK, S9X 1Z5

## Customer

Name PINERIDGE FORD SALES  
Address  
City MEADOW LAKE, SK  
Postal Code S9X 1Z5  
PhoneNumber (306) 236-1810(w)  
Email kevin@pineridgeford.com

## Inspection

Service Order 111292  
Advisor Ryan Uliski  
Tech Rick Arnold

## Exterior of the vehicle

vehicle modifications Pass     
Comments:  
exterior lights operational Fail     
Comments: fog lamp lens are scratched but both are operable.  
exterior damage Fail     
Comments: paint chips and rock rash  
windshield: cracked, chipped or sandblasted Pass     
Comments:  
windshield, driver and passenger front windows aftermarket tint Pass     
Comments:

## Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More  
Caution: 4/32" - 5/32"  
Fail: 3/32" or less  
Left front tire tread depth Pass     
Right front tire tread depth Pass     
Left rear tire tread depth Pass     
Right rear tire tread depth     
Inspect overall tire wear and condition  
Comments: all 12/32  
Wheel Retorque  
Wheel Torque Spec FT/LBS:

## Vehicle

VIN 1FTFW1EG4JFE51600  
Year 2018  
Make FORD  
Model F-150  
Engine 3.5L V6 ECOBOOST  
Fuel Gasoline  
Stock Number N7085A  
License/Stock  
Date In 01/30/2023 9:13:41 AM  
Completed Date 01/31/2023  
Odom 140752

## Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass     
Comments:  
Air Inlet system: air filter, filter box and inlet tube are clean Pass     
Comments:  
Emission System: visually inspect to ensure all components are intact with no modifications Pass     
Comments:  
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass     
Comments:  
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass     
Comments:  
Power Steering: pump, gear, and hoses have no leaks or damage Pass     
Comments:  
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass     
Comments:  
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass     
Comments:  
Brake System: no leaks or damage. Fluid is at proper level and clean Pass     
Comments:  
Inspect cabin air filter and report findings Fail     
Comments: suggest replacing

# PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH  
MEADOW LAKE, SK, S9X 1Z5

## Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering System and Linkage: no leaks damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension System: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Axles: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Exhaust System: no leaks, damage. All components in place including convertors	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Frame/Undercarriage: examine for damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Trailer Plug: harness intact, plug tested with trailer DR.	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments: : No				
Spare Tire, jack, and tools	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				

## Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)				
Cauton: 4mm-5mm (disc), 2mm (drum)				
Fail: 3mm or less (disc), 1mm (drum)				
Measure front brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Thickness: 8				
Measure rear brake lining thickness	Yellow	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Thickness: 4				
Inspect brake system components	Yellow	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake Rotor Thickness MM				
Left Rear:				
Right Rear:				
Left Front:				
Right Front:				

## Additional Recommendations

Additional Recommendations				
Comments:				

## Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Transmission Performance: shifts smoothly with no unusable noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering: steering is tight and responsive with no unusual characteristics or noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension: vehicle exhibits no sign of harshness or loose suspension	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
A/C and Heater: operating properly with no unusual noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Cruise Control: operating properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Vibration/Noise: no unusual vibration or noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Warning Lights - No warning lights illuminated while operating the vehicle	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Wipers/Washer: no streaks or inconsistent spray	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Gauges: working correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power Seats: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Lights: functioning correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Horn: operates correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Windows/Locks: operating correctly	Fail	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments: right rear window inoperative - repaired				
Mirrors- Operate correctly (power and manual)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Moonroof	Not Applicable	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Clock/Audio System	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Other Switches/Controls	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Heated Backglass	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power outlets work	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				