

# PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH  
MEADOW LAKE, SK, S9X 1Z5

## Customer

Name PINERIDGE FORD SALES  
Address BOX 2380  
City MEADOW LAKE, SK  
Postal Code S9X 1Z5  
PhoneNumber (306) 236-1810(w)  
Email ryan@pineridgeford.com

## Inspection

Service Order 108137  
Advisor Andrew Spencer  
Tech Rick Arnold

## Exterior of the vehicle

vehicle modifications Pass     
Comments:  
exterior lights operational Pass     
Comments:  
exterior damage Pass     
Comments:  
windshield: cracked, chipped or sandblasted Pass     
Comments:  
windshield, driver and passenger front windows aftermarket tint     
Comments:

## Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More  
Caution: 4/32" - 5/32"  
Fail: 3/32" or less  
Left front tire tread depth Pass     
Right front tire tread depth Pass     
Left rear tire tread depth Pass     
Right rear tire tread depth Pass     
Inspect overall tire wear and condition  
Comments: winter rims and tires ?

## Vehicle

VIN 1FMCU9G96HUB18113  
Year 2017  
Make FORD  
Model ESCAPE  
Engine 2.0L ECOBOOST GTDI I-4  
Fuel  
Stock Number N6932B  
License/Stock  
Date In 02/01/2022 2:26:16 PM  
Completed Date 02/07/2022  
Odom 167980

## Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass     
Comments:  
Air Inlet system: air filter, filter boxc and inlet tube are clean Pass     
Comments:  
Emission System: visually inspect to ensure all components are intact with no modifications Pass     
Comments:  
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass     
Comments:  
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass     
Comments:  
Power Steering: pump, gear, and hoses have no leaks or damage Pass     
Comments:  
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass     
Comments:  
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass     
Comments:  
Brake System: no leaks or damage. Fluid is at proper level and clean Pass     
Comments:  
Inspect cabin air filter and report findings Pass     
Comments:

# PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH  
MEADOW LAKE, SK, S9X 1Z5

## Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:			
Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Brake System: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Steering System and Linkage: no leaks damage or wear	Fail	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments: front stab links			
Suspension System: no leaks, damage, or wear	Fail	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments: front sway bar bushings			
Axles: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Exhaust System: no leaks, damage. All components in place including convertors	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Frame/Undercarriage: examine for damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Trailer Plug: harness intact, plug tested with trailer DR.	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments: : No			
Spare Tire, jack, and tools	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			

## Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)			
Cauton: 4mm-5mm (disc), 2mm (drum)			
Fail: 3mm or less (disc), 1mm (drum)			
Measure front brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Measure rear brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspect brake system components	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>

## Additional Recommendations

Additional Recommendations			
Comments:			

## Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Transmission Performance: shifts smoothly with no unusable noise	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Steering: steering is tight and responsive with no unusual characteristics or noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Suspension: vehicle exhibits no sign of harshness or loose suspension	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
A/C and Heater: operating properly with no unusual noises	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Cruise Control: operating properly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Vibration/Noise: no unusual vibration or noise	Fail	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments: slight vibration at 100kmh ,tire balance ?			
Instrument Warning Lights - No warning lights illuminated while operating the vehicle	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Wipers/Washer: no streaks or inconsistent spray	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Instrument Guages: working correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Power Seats: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Lights: functioning correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Horn: operates correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Windows/Locks: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Mirrors- Operate correctly (power and manual)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Moonroof	Not Applicable	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments:			
Clock/Audio System	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Other Switches/Controls	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Heated Backglass	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			
Power outlets work	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			