

SO # 108932

SERVICE ORDER
INTERNAL COPY



Printed 06/20/2022 12:52:44 PM

User 118 Page 1

Customer No

Home Cell Email

Bus Today

Term CASH

Advisor	Ryan Uliski	Promised	05/06/2022 7:11 PM	Tag
Shop	S1	Opened	05/06/2022 3:29 PM	Location
Priority	1000	Cashiered	06/14/2022 4:59 PM	PO #

License No	Odometer In	Odometer Out	InServ Date	Stock No
	92013	92013	06/13/2018	N6997A
Year	Make	Model	Model No	Colour
2018	FORD	EXPLORER	K8G	WHITE
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FM5K8GT0JGB61290	01	FORD		
Engine Size	3.5L V6 ECOBOOST	Fleet #		

Request	Description	Job	CSR	Status
003-DIAG	noise in front end	1	213	Original
Labour	Description	Type	Tech	Amount
003-DIAG	noise in front end	I	96	41.40
Technician	96 -			Parts Total 0.00
Cause	noise when going over bumps			Labour Total 41.40
Correction	noise is coming from the rear sway bar links need to replace them			Request Total 41.40

Request	Description	Job	CSR	Status
015-ESP99P	USED INSPECTION Includes: Safety Inspection, Mechanical Inspection, Body and Trim Inspection, and Engine Oil and Filter (PARTS EXTRA)	2	118	Approved
Labour	Description	Type	Tech	Amount
L-ESP99P	LABOUR - ESP USED VEHICLE INSPECTION	I	96	193.20
Technician	96 -			Parts Total 0.00
Cause	used inspection			Labour Total 193.20
Correction	used inspection			Request Total 193.20

Request	Description	Job	CSR	Status
016-BRONZE	BRONZE CLEAN - MID TO HEAVY CLEAN (With Light Steam) Includes: Exterior Wash/Shammy Windows Inside/Outside Vacuum Seats/Floors Wipe Down Interior Spray Vinyl Mats Wipe Down Engine Compartment Chrome Shine	3	118	Approved
Labour	Description	Type	Tech	Amount
016-BRONZE	BRONZE CLEAN - MID TO HEAVY CLEAN (With Light Steam) Includes: Exterior Wash/Shammy Windows Inside/Outside Vacuum Seats/Floors Wipe Down Interior Spray Vinyl Mats Wipe Down Engine Compartment Chrome Shine	IDET	217	319.00
Technician	217 -			Parts Total 0.00
Cause	.			Labour Total 319.00
Correction	.			Request Total 319.00

Request	Description	Job	CSR	Status		
000-NOISE	replace rear stab links	4	213	Approved		
Labour	Description	Type	Tech	Amount		
000-NOISE	replace rear stab links	I	137	75.75		
Part	Description	Shp	Bin	Type	Price	Amount
MEF 158	LINK - STABILIZER BA	1	D18	I	122.99	122.99
MEF 157	LINK - STABILIZER BA	1	D18	I	106.99	106.99
W520213 S440	NUT	4	E21	I	15.99	63.96
Technician	137 -					Parts Total 293.94
Cause	replace rear stab links					Labour Total 75.75
Correction	Replaced rear stab links done.					Request Total 369.69

Request	Description	Job	CSR	Status
000-INFO	back-up camera is foggy	5	213	Approved
Labour	Description	Type	Tech	Amount
000-INFO	back-up camera is foggy	I	999	0.00

INTERNAL COPY
SERVICE ORDER

Customer No

Advisor Ryan Ullski
Shop S1
Priority 1000
Promised 05/06/2022 7:11 PM
Tag 05/06/2022 3:29 PM
Location 08/14/2022 4:59 PM
PO #

Home Cell Email

Bus Today

Term CASH

License No 92013
Odometer In 92013
Odometer Out 06/13/2018
Inserv Date 06/13/2018
Model No N6997A
Model K8G
Year Make 2018 FORD
Vehicle ID No 1FM5K8GT0JGB1290 01
Selling Dealer EXPLORER
Extended Warranty FORD
Colour WHITE
Stock No N6997A

Engine Size 3.5L V6 ECOBOOST
Fleet #

Part	Description	Shp	Bin	Type	Price	Amount
000-INFO	back-up camera is foggy				137	101.00
Part	GB52 19G490 C	1	SPORD	1	596.99	596.99
Technician	137 -					
Cause	back-up camera is foggy					
Correction	Replaced back up camera done.					
	Perform lin module initialization IPM-B done.					
Request	Description	Job	CSR	Status		
S-SUBLET	SUBLET	6	202	Approved		
Labour	Description	Type	Tech	Amount		
S-SUBLET	SUBLET	1	999	0.00		
Sublet	Description	Type	CSR	Amount		
8793.1	20622/MR. GLASS LTD/SUBLET	ISUB	202	653.00		
Technician	999 -					
Cause	sublet done					
Correction						

Request	Description	Job	CSR	Status	Amount
S-SUBLET	SUBLET	6	202	Approved	
Labour	Description	Type	Tech	Amount	
S-SUBLET	SUBLET	1	999	0.00	
Sublet	Description	Type	CSR	Amount	
8793.1	20622/MR. GLASS LTD/SUBLET	ISUB	202	653.00	
Technician	999 -				
Cause	sublet done				
Correction					

Summary	Pay Type	Labour	Parts	Fees	Misc	Supplies	Sublet	Env	Ded	GST	PST	Total
C	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
W	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
I	730.35	730.35	890.93	0.00	0.00	64.46	653.00	0.00	0.00	0.00	0.00	2,338.74
Total	730.35	730.35	890.93	0.00	0.00	64.46	653.00	0.00	0.00	0.00	0.00	2,338.74

INTERNAL	ACCOUNT	DESCRIPTION	TYPE	CONTROL #	AMOUNT	COMMENTS
P136000	INV-USED TRUCKS			N6997A	2338.74	B61290 - 2018 FORD EXPLORER SPORT
					4WD	

