

# PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH  
MEADOW LAKE, SK, S9X 1Z5

## Customer

Name  
Address  
City  
Postal Code  
PhoneNumber  
Email

## Vehicle

VIN 1FM5K8GT0JGB61290  
Year 2018  
Make FORD  
Model EXPLORER  
Engine 3.5L V6 ECOBOOST  
Fuel  
Stock Number N6997A  
License/Stock  
Date In 05/11/2022 9:26:39 AM  
Completed Date 06/10/2022  
Odom 92013

## Inspection

Service Order 108932  
Advisor Andrew Spencer  
Tech Tyson B

## Exterior of the vehicle

vehicle modifications Pass     
Comments:  
exterior lights operational Pass     
Comments:  
exterior damage Pass     
Comments:  
windshield: cracked, chipped or sandblasted Fail     
Comments: rock chip  
windshield, driver and passenger front windows aftermarket tint Pass     
Comments:

## Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass     
Comments:  
Air Inlet system: air filter, filter box and inlet tube are clean Pass     
Comments:  
Emission System: visually inspect to ensure all components are intact with no modifications Pass     
Comments:  
Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass     
Comments:  
Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass     
Comments:  
Power Steering: pump, gear, and hoses have no leaks or damage Pass     
Comments:  
Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass     
Comments:  
Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises Pass     
Comments:  
Brake System: no leaks or damage. Fluid is at proper level and clean Pass     
Comments:  
Inspect cabin air filter and report findings Pass     
Comments:

## Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More

Caution: 4/32" - 5/32"

Fail: 3/32" or less

Left front tire tread depth Pass     
Right front tire tread depth Pass     
Left rear tire tread depth Pass     
Right rear tire tread depth Pass     
Inspect overall tire wear and condition  
Comments: LF 9/32" RF 9/32" RR 7/32" LR 7/32"  
Wheel Retorque  
Wheel Torque Spec FT/LBS:

**PINERIDGE FORD VEHICLE REPORT CARD**  
 413 HIGHWAY 4 SOUTH  
 MEADOW LAKE, SK, S9X 1Z5

**Under the Vehicle**

Transmission or Transfer Case: no leaks, damage or wear Pass     
 Comments:

Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear Pass     
 Comments:

Brake System: no leaks, damage or wear Pass     
 Comments:

Steering System and Linkage: no leaks damage or wear Pass     
 Comments:

Suspension System: no leaks, damage, or wear Pass     
 Comments:

Axles: no leaks, damage or wear Pass     
 Comments:

Exhaust System: no leaks, damage. All components in place including convertors Pass     
 Comments:

Frame/Undercarriage: examine for damage or wear Pass     
 Comments:

Trailer Plug: harness intact, plug tested with trailer DR.     
 Comments:  
 : Yes

Spare Tire, jack, and tools Pass     
 Comments:

**Measure and Inspect Brake Lining and Condition**

Pass: 6mm or greater (disc), 3mm and Greater (drum)  
 Caution: 4mm-5mm (disc), 2mm (drum)  
 Fail: 3mm or less (disc), 1mm (drum)

Measure front brake lining thickness Pass     
 Thickness:

Measure rear brake lining thickness Pass     
 Thickness:

Inspect brake system components Pass     
 Brake Rotor Thickness MM

Left Rear:  
 Right Rear:  
 Left Front:  
 Right Front:

**Additional Recommendations**

Additional Recommendations  
 Comments:

**Vehicle Interior Checks & Road Test**

Engine Performance: no problems (starting, poor performance, or smoking) Pass     
 Comments:

Transmission Performance: shifts smoothly with no unusable noise Pass     
 Comments:

Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly Pass     
 Comments:

Steering: steering is tight and responsive with no unusual characteristics or noises Pass     
 Comments:

Suspension: vehicle exhibits no sign of harshness or loose suspension Pass     
 Comments:

A/C and Heater: operating properly with no unusual noises Pass     
 Comments:

Cruise Control: operating properly Pass     
 Comments:

Vibration/Noise: no unusual vibration or noise Pass     
 Comments:

Instrument Warning Lights - No warning lights illuminated while operating the vehicle Pass     
 Comments:

Wipers/Washer: no streaks or inconsistent spray Pass     
 Comments:

Instrument Gauges: working correctly Pass     
 Comments:

Power Seats: operating correctly Pass     
 Comments:

Lights: functioning correctly Pass     
 Comments:

Horn: operates correctly Pass     
 Comments:

Windows/Locks: operating correctly Pass     
 Comments:

Mirrors- Operate correctly (power and manual) Pass     
 Comments:

Moonroof Pass     
 Comments:

Clock/Audio System Pass     
 Comments:

Other Switches/Controls Pass     
 Comments:

Heated Backglass Pass     
 Comments:

Power outlets work Pass     
 Comments: