

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Customer

Name PINERIDGE FORD SALES
Address BOX 2380
City MEADOW LAKE, SK
Postal Code S9X 1Z5
PhoneNumber (306) 236-1810(w)
Email kevin@pineridgeford.com

Inspection

Service Order 109660
Advisor Ryan Uliski
Tech Damon Stomp

Inspect Lighting

Inspect instrument cluster warning lamps Pass/Done

Comments:

Inspect headlight low and high beam operation Pass/Done

Comments:

Inspect fog/driving lights (if equipped) Pass/Done

Comments:

Inspect taillight, turn signal, side marker, and license plate lights Pass/Done

Comments:

Inspect taillight, turn signal, and side marker assemblies for cracks and damage Pass/Done

Comments:

Inspect brake light operation Pass/Done

Comments:

Inspect hazard light operation Pass/Done

Comments:

Inspect reverse light operation Pass/Done

Comments:

Inspect dash and interior lights Pass/Done

Comments:

Inspect Components

Inspect mirror glass Pass/Done

Comments:

Windshield for cracks, chips and pitting Pass/Done

Comments:

Inspect heating and air conditioning operation Pass/Done

Comments:

Inspect all vehicle wiper blades Pass/Done

Comments:

Check horn operation Pass/Done

Comments:

Vehicle

VIN 1FTFW1ED5MFB82646
Year 2021
Make FORD
Model F-150
Engine 3.5L POWERBOOST FULL-HYBRID V6
Fuel
Stock Number 0U7050
License/Stock
Date In 07/28/2022 10:12:41 AM
Completed Date 08/17/2022
Odom 28785

Inspect Under Hood Fluid Levels, Condition

Check engine oil level and condition Pass/Done

Comments:

Check transmission fluid level and condition Not Applicable

Comments:

Check brake fluid level and condition Pass/Done

Comments:

Check engine coolant level and condition Pass/Done

Comments:

Check power steering fluid level and condition Not Applicable

Comments:

Fill windshield washer fluid Pass/Done

Comments:

Inspect Under Hood Components

Inspect hood struts Pass/Done

Comments:

Inspect battery terminals and cables Pass/Done

Comments:

Inspect air filter Pass/Done

Comments:

Inspect air induction system Pass/Done

Comments:

Inspect all hoses and clamps Pass/Done

Comments:

Inspect drive belts Pass/Done

Comments:

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Measure and Inspect Tire Tread Depth and Condition

6/32" or More = Pass

4/32" - 5/32" = Caution

3/32" or Less = Fail

Left front tire tread depth Pass/Done

Comments: 12/32

Right front tire tread depth Pass/Done

Comments: 12/32

Left rear tire tread depth Pass/Done

Comments: 12/32

Right rear tire tread depth Pass/Done

Comments: 12/32

Inspect overall tire wear and condition Pass/Done

Comments:

Check and adjust front tire pressure Pass/Done

Comments: 36 psi

Check and adjust rear tire pressure Pass/Done

Comments: 36 psi

Wheel Retorque

Wheel Torque Spec FT/LBS:

Measure and Inspect Brake Linings and Condition

Pass: 6mm and Greater (disc), 3mm and Greater (drum)

Caution: 4mm - 5mm (disc), 2mm (drum)

Fail: 3mm or Less (disc), 1mm or less (drum)

Measure front brake lining thickness Pass/Done

Comments: 12mm
Thickness:

Measure rear brake lining thickness Pass/Done

Comments: 8mm
Thickness:

Inspect brake system components Pass/Done

Comments:

Brake Rotor Thickness MM

Left Rear:
Right Rear:
Left Front:
Right Front:

Inspect Drive Train Fluid Levels, Condition and Leaks

Inspect front differential and check for leaks Fail

Comments: front differential opinion seal is leaking

Inspect rear differential and check for leaks Pass/Done

Comments:

Inspect transfer case and check for leaks Pass/Done

Comments:

Inspect Under Vehicle Components

Inspect fuel tank, lines and connections Pass/Done

Comments:

Inspect exhaust system for leaks, damage, and loose parts Pass/Done

Comments:

Inspect engine mounts Pass/Done

Comments:

Inspect transmission mounts Pass/Done

Comments:

Inspect steering components Pass/Done

Comments:

Inspect sway bar components Pass/Done

Comments:

Inspect for wheel bearing free play Pass/Done

Comments:

Inspect front suspension components Pass/Done

Comments:

Inspect rear suspension components Pass/Done

Comments:

Inspect axles, driveshaft(s), U-joints and CV joints/boots Fail

Comments: front right axle boot is ripped

Inspect Spare tire Pass

Comments: No

Inspect for fluid leaks

Inspect for engine oil leaks Pass/Done

Comments:

Inspect cooling system for leaks Pass/Done

Comments:

Inspect brake system for leaks Pass/Done

Comments:

Inspect transmission for leaks Pass/Done

Comments:

Inspect transfer case seals/PTU seals for leaks Pass/Done

Comments:

Inspect steering system for leaks Pass/Done

Comments:

Additional Recommendations

additional recommendations

Comments: