

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Customer

Name PINERIDGE FORD SALES
Address BOX 2380
City MEADOW LAKE, SK
Postal Code S9X 1Z5
PhoneNumber (306) 236-1810(w)
Email kevin@pineridgeford.com

Inspection

Service Order 110079
Advisor Ryan Uliski
Tech Rick Arnold

Exterior of the vehicle

vehicle modifications

Comments: blacked out tail lights. right tail light loose

exterior lights operational Fail

Comments: right licence light inoperative

exterior damage Pass

Comments:

windshield: cracked, chipped or sandblasted Pass

Comments:

windshield, driver and passenger front windows aftermarket tint

Comments:

Measure and Inspect Tire Tread Depth and Condition

Pass: 6/32" or More

Caution: 4/32" - 5/32"

Fail: 3/32" or less

Left front tire tread depth Pass

Right front tire tread depth Pass

Left rear tire tread depth Pass

Right rear tire tread depth Pass

Inspect overall tire wear and condition

Comments: all 7/32

Wheel Retorque

Wheel Torque Spec FT/LBS:

Vehicle

VIN 1FTFW1E55KFC89525
Year 2019
Make FORD
Model F-150
Engine 5.0L V8
Fuel
Stock Number N7060A
License/Stock
Date In 09/12/2022 11:44:21 AM
Completed Date 10/12/2022
Odom 97689

Under The Hood

Engine: examine for leaks, damage and abnormal noises, oil condition and oil level Pass

Comments:

Air Inlet system: air filter, filter box and inlet tube are clean Pass

Comments:

Emission System: visually inspect to ensure all components are intact with no modifications Pass

Comments:

Radiator/Cooling System: no leak, damage or wear to the water pump, overflow bottle, hoses, fan, coolant is in good condition and full Pass

Comments:

Automatic Transmission: no leaks, or damage. Fluid is in good condition and correct level Pass

Comments:

Power Steering: pump, gear, and hoses have no leaks or damage Pass

Comments:

Electrical: cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications Pass

Comments:

Air Conditioning: compressor, clutch and hoses have no leaks, damage, or unusual noises

Comments:

Brake System: no leaks or damage. Fluid is at proper level and clean Pass

Comments:

Inspect cabin air filter and report findings Fail

Comments: cabin filter

PINERIDGE FORD VEHICLE REPORT CARD

413 HIGHWAY 4 SOUTH
MEADOW LAKE, SK, S9X 1Z5

Under the Vehicle

Transmission or Transfer Case: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Half Shaft and CV Joints or Drive Shaft and U-Joints: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering System and Linkage: no leaks damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension System: no leaks, damage, or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Axles: no leaks, damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Exhaust System: no leaks, damage. All components in place including convertors	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Frame/Undercarriage: examine for damage or wear	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Trailer Plug: harness intact, plug tested with trailer DR.		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments: : No				
Spare Tire, jack, and tools	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				

Measure and Inspect Brake Lining and Condition

Pass: 6mm or greater (disc), 3mm and Greater (drum)				
Cauton: 4mm-5mm (disc), 2mm (drum)				
Fail: 3mm or less (disc), 1mm (drum)				
Measure front brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Thickness: 7				
Measure rear brake lining thickness	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Thickness: 6				
Inspect brake system components	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Rotor Thickness MM				
Left Rear:				
Right Rear:				
Left Front:				
Right Front:				

Additional Recommendations

Additional Recommendations
Comments: cover for rear ac outlet missing
no mud flaps

Vehicle Interior Checks & Road Test

Engine Performance: no problems (starting, poor performance, or smoking)		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Transmission Performance: shifts smoothly with no unusable noise		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Brake System: vehicle brakes without any issues (e.g. drift, pull, noise, vibration, etc). Parking brake functions properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Steering: steering is tight and responsive with no unusual characteristics or noises		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Suspension: vehicle exhibits no sign of harshness or loose suspension		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
A/C and Heater: operating properly with no unusual noises		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Cruise Control: operating properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Vibration/Noise: no unusual vibration or noise		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Warning Lights - No warning lights illuminated while operating the vehicle	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Wipers/Washer: no streaks or inconsistent spray	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Instrument Guages: working correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power Seats: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Lights: functioning correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Horn: operates correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Windows/Locks: operating correctly	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Mirrors- Operate correctly (power and manual)	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Moonroof	Not Applicable	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:				
Clock/Audio System	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Other Switches/Controls	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Heated Backglass	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				
Power outlets work	Pass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments:				